Name of Work :-Improvements to RCC Drains and RCC Culverts at Right Side Roads of 1st Main Road Kuvempu Nagara, and Surrounding area in Ward No.05



Assistant Engineer
Ward No.05

Assistant Executive Engineer
Byatarayanapura Sub Division

Scanned with CamScanner

Name of Work :-Improvements to RCC Drains and RCC Culverts at Right Side Roads of 1st Main Road Kuvempu Nagara, and Surrounding area in Ward No.05

Assistant Engineer
Ward No.05

Assistant Executive Engineer
Byatarayanapura Sub Division

Scanned with CamScanner

Name of Work :-Improvements to RCC Drains and RCC Culverts at Right Side Roads of 1st Main Road Kuvempu Nagara, and Surrounding area in Ward No.05

Assistant Engineer
Ward No.05

Assistant Executive Engineer
Byatarayanapura Sub Division

Scanned with CamScanner

Name of Work :-Improvements to RCC Drains and RCC Culverts at Right Side Roads of 1st Main Road Kuvempu Nagara, and Surrounding area in Ward No.05

Assistant Engineer
Ward No.05

Assistant Executive Engineer
Byatarayanapura Sub Division

Scanned with CamScanner

Name of Work :-Improvements to RCC Drains and RCC Culverts at Right Side Roads of 1st Main Road Kuvempu Nagara, and Surrounding area in Ward No.05

Assistant Engineer
Ward No.05

Assistant Executive Engineer
Byatarayanapura Sub Division

Scanned with CamScanner

Name of Work :-Improvements to RCC Drains and RCC Culverts at Right Side Roads of 1st Main Road Kuvempu Nagara, and Surrounding area in Ward No.05

Assistant Engineer
Ward No.05

Assistant Executive Engineer
Byatarayanapura Sub Division

Scanned with CamScanner

Name of Work :-Improvements to RCC Drains and RCC Culverts at Right Side Roads of 1st Main Road Kuvempu Nagara, and Surrounding area in Ward No.05

Assistant Engineer
Ward No.05

Assistant Executive Engineer
Byatarayanapura Sub Division

Scanned with CamScanner

Name of Work :-Improvements to RCC Drains and RCC Culverts at Right Side Roads of 1st Main Road Kuvempu Nagara, and Surrounding area in Ward No.05





Assistant Engineer
Ward No.05

Assistant Executive Engineer
Byatarayanapura Sub Division

Scanned with CamScanner

Name of Work :-Improvements to RCC Drains and RCC Culverts at Right Side Roads of 1st Main Road Kuvempu Nagara, and Surrounding area in Ward No.05



Assistant Engineer
Ward No.05

Assistant Executive Engineer
Byatarayanapura Sub Division

Scanned with CamScanner

Name of Work :-Improvements to RCC Drains and RCC Culverts at Right Side Roads of 1st Main Road Kuvempu Nagara, and Surrounding area in Ward No.05

Assistant Engineer
Ward No.05

Assistant Executive Engineer
Byatarayanapura Sub Division

Scanned with CamScanner